PA RME Wiring Diagram

Remote Mounting Kit for PA 5AV